



1718 W. Fullerton Chicago, IL 60614
 Ph: 773.770.1195 • Fax: 773.935.5613
 www.PureEdgeLighting.com • info@PureEdgeLighting.com
 © 2016 PureEdge Lighting. All Rights Reserved.


Installation Instructions for 4" Round & Square 2 Port Fast Jack LED Power Canopy




IMPORTANT INFORMATION

- This product is ETL listed for indoor dry locations.
- The product can be installed to a 4" electrical box with round plaster ring, or to an octagon electrical box.
- Minimum electrical box volume must be 6 cubic inches (98 cubic centimeters).
- For dimming information visit www.edgelighting.com.
- This product can be used with LED or halogen Fast Jack fixtures.


SAVE THESE INSTRUCTIONS!




Install the Canopy



- 1: Turn the power to the electrical box off.
- 2: Connect the white transformer wire to the neutral power wire with a wire nut.
- 3: Connect the black transformer wire to the hot power wire with a wire nut.
- 4: Place the transformer and transformer wires inside the electrical box.





- 5: Connect one wire of each Fast Jack port to one transformer wire (either one) with a wire nut.
- 6: Connect the other wire of each port to the other transformer wire with a wire nut.



7: Place all wires inside the electrical box.

8: Secure the Fast Jack assembly mounting plate to the electrical box by tightening the two provided #8-32 screws.

9: Place the canopy holes onto the Fast Jack ports against the electrical box and secure it in place by tightening the knurled caps to the Fast Jack ports. **Make sure the knurled caps are not cross threaded.**



CAUTION: Risk of Fire: Max load of Fast Jack LED canopy is **60** watt.

10: Use fingers to tighten the Fast Jack fixture connector into the Fast Jack canopy ports.